

# Amine Test

Order No. 81 01 061

## Application Range

Standard Measuring Range:	qualitative
Number of Strokes n:	1
Time for Measurement:	approx. 5 s
Standard Deviation:	± 30 %
Color Change:	yellow → blue

## Ambient Operating Conditions


Temperature:	0 to 40 °C
Absolute Humidity:	3 to 15 mg H <sub>2</sub> O / L

## Reaction Principle

Amine + pH indicator → blue reaction product

## Cross Sensitivity

The tube indicates unspecifically basic reacting gases with different sensitivities. It is impossible to differentiate between the basic reacting gases.



D-13318/2010



*Northside Sales, Co.*

Safety & Industrial Products

800-467-9005